


## Appliance information

### Image with EI141



### Use


Indication of silo filling levels.

Values (4 ... 20 mA) measured by **MOLOSbob** and **MOLOSwave** are displayed as filling level in percentage.

### Features

- Indication of filling levels in silos with LED indicators EI141 integrated in an electrical cabinet and supplemented in accordance with customers request
- Connection of MOLOSbob and MOLOSwave
- Level indication in % of the filling height
- Any amount of analog inputs
- Design as indication device only or with connection and energising of the level measurement devices
- Switch for „Start measurement“ and „EMERGENCY-STOP“ integrated

### Image with EI7412




### Option relay

- Indication of filling levels in silos with LED indicators EI7412
- 2 relay adjustable within the measuring range per measuring point
- Signal contact e.g. for demand (trigger for an order)
- Alarm contact for empty indication
- Normally open contact, 250V AC/ 8A (cosPhi=1)

## Appliance information

### Image



### Option additional functions

Additional functions integrated in silo level indication:

- Indication of point level e.g. „silo full“, „demand“ or „silo empty“ with connection opportunity for filling level switches
- Installation of functions of the silo overload protection MOLOSsafe
- Connection terminals for horn or signal lamp, jet filter, filling device and couplings with limit switch